

## 2019 V.03 NEW PRODUCTS

### Tenacity Auto Parts Co., Ltd.

| Part NO.   | OEM No.       | Model  | Year  | Description                                | Picture   | Make   |
|------------|---------------|--|-------|--|---|--------|
| ASMAU1001K | 431412249DK   | AUDO 100   | .     | Strut mount with Bearing, Front LH/RH      |    | AUDI   |
| ABTDW1001  | 96103222      | LANOS 1.4/1.5/1.6<br>CIELO<br>LEMANS<br>AVEO 1.4<br>ESPERO<br>NUBIRA 1.6<br>REZZO 1.6<br>TACUMA 1.6<br>NEXIA 1.5/1.8<br>CHEVROLET AVEO 1.4 | .     | Guide Pulley, Timing belt, NTN Bearing     |    | DAEWOO |
| AWSFO1123  | AB39-6B032-MB | RANGER   | 12-15 | Engine mount, Front                        |    | FORD   |
| ABTFO1016  | 95WF19A216A A | FOCUS I<br>ESCORT VII<br>FIESTA BOX<br>COURRIER<br>FIESTA IV.V<br>GALAXY I<br>KA<br>PUMA   | .     | Guide Pulley, V-belt, NTN Bearing          |   | FORD   |
| ABTFO1017  | 25287-2A010   | VRN NEW 1.5TDCI  | .     | Guide Pulley, V-belt, NTN Bearing          |  | FORD   |
| ABTFO1018  | YS7Z-6M250-BA | FOCUS 2.0<br>ESCAPE 2.0  | .     | Tensioner Pulley, Timing belt, NTN Bearing |  | FORD   |
| AWSHO1160  | 50820-T0T-H01 | CR-V 2.4   | 12-14 | Engine mount, RH                           |  | HONDA  |
| AWSHO1164  | 50820-TR0-A81 | CIVIC  | 12-15 | Engine mount, RH, Hydraulic                |  | HONDA  |
| ABTHO1017  | 14520-PFB-003 | ACCORD 2.0<br>CIVIC 2.0  | .     | Guide Pulley, Timing belt, NTN Bearing     |  | HONDA  |

## 2019 V.03 NEW PRODUCTS

### Tenacity Auto Parts Co., Ltd.

| Part NO.  | OEM No.       | Model  | Year                     | Description                                      | Picture   | Make             |
|-----------|---------------|--|--------------------------|--|---|------------------|
| ABTH01018 | 14510-PR3-003 | CIVIC CRX<br>CIVIC DEL SOL   | .                        | Tensioner Pulley,<br>Timing belt, NTN<br>Bearing |    | HONDA            |
| ABTH01016 | 25286-37100   | GRANDEUR<br>SKYLARK<br>SANTA SONATA<br>TUCSON.XG                                   | .                        | Guide Pulley, V-belt,<br>NTN Bearing             |    | HONDA<br>HYUNDAI |
| ABTHY1019 | 24810-26010   | ACCENT   | .                        | Guide Pulley, Timing<br>belt, NTN Bearing        |    | HYUNDAI          |
| ABTHY1022 | 25281-3C100   | AZERA 3.3<br>SANTA FE 3.3<br>KIA CADENZA 3.3<br>KIA SEDONA 3.3                     | 14-<br>14-<br>15-<br>15- | Tensioner Pulley,<br>V-belt, NTN Bearing         |    | HYUNDAI          |
| ABTHY1021 | 24810-37100   | COUPE<br>SANTA FE 2.7<br>SONATA 2.5/2.7  | .                        | Tensioner Pulley,<br>Timing belt, NTN<br>Bearing |   | HYUNDAI          |
| ABTHY1011 | 97834-22100   | ELANTRA<br>ACCENT<br>VERNA III<br>i30  | .                        | Tensioner Pulley, V-<br>belt, NTN Bearing        |  | HYUNDAI          |
| ABTHY1017 | 24810-23011   | ELANTRA 1.8/2.0<br>AVANTE 1.8/2.0<br>COUPE 1.6/2.0<br>LANTRA 1.8/2.0<br>MATRIX 1.8 | .                        | Guide Pulley, Timing<br>belt, NTN Bearing        |  | HYUNDAI          |
| ABTHY1018 | 25286-3C100   | GRANDEUR<br>SONATA   | .                        | Guide Pulley, V-belt,<br>NTN Bearing             |  | HYUNDAI          |
| ABTHY1013 | 25286-2B000   | i30  | .                        | Guide Pulley, V-belt,<br>NTN Bearing             |  | HYUNDAI          |
| ABTHY1015 | 25287-25000   | ix35<br>SONATA   | .                        | Guide Pulley, V-belt,<br>NTN Bearing             |  | HYUNDAI          |
| ABTHY1023 | 25281-3A000   | ix55<br>VERACRUZ   | 07-<br>06-               | Tensioner Pulley,<br>V-belt, NTN Bearing         |  | HYUNDAI          |

# 2019 V.03 NEW PRODUCTS

## Tenacity Auto Parts Co., Ltd.

| Part NO.  | OEM No.  | Model  | Year                    | Description                                | Picture   | Make      |
|-----------|--|--|-------------------------|--|---|-----------|
| ABTHY1012 | MD050135<br>MD050137<br>MD329625<br>24317-42000<br>24317-42020<br>23357-41010<br>24317-42010 | L200/L300<br>DELICA 2.3/2.5<br>PAJERO 2.0/2.3/2.5<br>TRITON 2.3/2.5<br>GALANT WAGON MAGNA 3.0<br>GRACE 2.5<br>PORTER 2.5 | .                       | Tensioner Pulley,<br>Timing belt           |    | HYUNDAI   |
| ABTHY1014 | MD050125   | L200/L300<br>DELICA<br>DIESEL MONTE<br>PAJERO 2.0/2.3/2.5<br>GALANT STATINO WAGON<br>GRACE PORTER 2.4                    | .                       | Tensioner Pulley,<br>Timing belt           |    | HYUNDAI   |
| ABTHY1016 | 24450-37100  | SANTA 2.7<br>SONATA 2.5/2.7<br>TIBURON 2.7<br>TUCSON 2.7<br>MAGENTIS 2.5/2.7<br>OPTIMA 2.5/2.7<br>SPORTAGE 2.7           | .                       | Guide Pulley, Timing<br>belt, NTN Bearing  |   | HYUNDAI   |
| ABTHY1020 | 6652000070   | SSANGYONG KYRON 2.0<br>SSANGYONG ACTYON 2.0<br>SSANGYONG REXTON 2.0/2.7  | .                       | Tensioner Pulley,<br>V-belt, NTN Bearing   |  | SSANGYONG |
| ASBIS1001 | 8-98161446-0   | D-MAX  | 12-                     | Bushing, Stabilizer                        |  | ISUZU     |
| ABTLE1001 | 16604-50030  | LEXUS  | .                       | Guide Pulley, V-belt,<br>NTN Bearing       |  | LEXUS     |
| ABRMA1012 | GA5R-34-38X  | PROTEGE<br>626<br>MX-6   | 95-98<br>93-97<br>93-97 | Bearing, Shock<br>absorber, Front<br>LH/RH |  | MAZDA     |
| ABTMA1011 | KL01-12-730  | 626 2.5<br>MX-6 2.5<br>PROBE 2.5   | .                       | Guide Pulley, Timing<br>belt               |  | MAZDA     |


## 2019 V.03 NEW PRODUCTS

### Tenacity Auto Parts Co., Ltd.

| Part NO.  | OEM No.       | Model  | Year                     | Description                                      | Picture   | Make                |
|-----------|---------------|--|--------------------------|--|---|---------------------|
| ABTMA1009 | KK150-12-700A | MAZDA 121/323<br>LASER 1.3/1.5/1.6/1.8<br>MAZDA PROTÉGÉ 1.8<br>AVELLA/CAPITAL 1.3/1.5<br>CAPITAL AVELLA<br>PRIDE   | 88-<br>88-<br>92-<br>94- | Tensioner Pulley,<br>Timing belt, NTN<br>Bearing |    | MAZDA               |
| ABTMA1010 | S55015980     | MAZDA 2<br>CX-3 1.5  | 15-<br>16-               | Tensioner Pulley,<br>V-belt, NTN Bearing         |    | MAZDA               |
| ABTMA1012 | SH01-15-980D  | MAZDA 3  | .                        | Tensioner Pulley,<br>V-belt, NTN Bearing         |    | MAZDA               |
| ACBMM1024 | MR953922      | OUTLANDER<br>AIRTREK   | 02-06<br>01-05           | Center bearing<br>support                        |   | 30.00<br>MITSUBISHI |
| ACBMM1025 | MR953919      | OUTLANDER<br>AIRTREK   | 02-06<br>01-05           | Center bearing<br>support                        |  | 30.00<br>MITSUBISHI |
| ABTMM1021 | MD11536       | L200 2.0/2.4<br>CORDIA, 1.8<br>GALANT 2.0/2.4<br>LANCER 2.0<br>PAJERO 2.4<br>WAGON 2.0<br>SAPORO 2.0<br>SPACE WAGON 2.0<br>STARION 2.0<br>TREDIA 1.8<br>GRACE 2.4<br>H-1 2.4<br>H100 2.4 | .                        | Tensioner Pulley,<br>Timing belt                 |  | MITSUBISHI          |
| ABTMM1023 | 1145A020      | LANCER   | .                        | Guide Pulley, Timing<br>belt, NTN Bearing        |  | MITSUBISHI          |
| ABTMM1020 | 1341A005      | OUTLANDER 2.0<br>FORTIS 1.8/2.0  | .                        | Guide Pulley, V-belt,<br>NTN Bearing             |  | MITSUBISHI          |

## 2019 V.03 NEW PRODUCTS

### Tenacity Auto Parts Co., Ltd.

| Part NO.   | OEM No.   | Model   | Year                                   | Description                                | Picture   | Make                 |
|------------|---|---|--|--|---|----------------------|
| ABTMI1022  | MD368210  | PAJERO 3.5/3.8  | .                                      | Guide Pulley, V-belt, NTN Bearing          |    | MITSUBISHI           |
| ABRNI1010  | 54325-31U01   | ELGRAND E50 3.5<br>TERRANO R50<br>MAXIMA 3.0<br>CEFIRO A32                          | 00-95-02<br>95-99<br>97-00             | Bearing, Shock absorber, Front LH/RH       |    | NISSAN<br>MITSUBISHI |
| ASMOP1003K | 344514K   | VECTRA 2.0  | 90-96                                  | Strut mount with Bearing, Front LH/RH      |    | OPEL                 |
| ASMPE1001K | 5038.40K  | 206   | .                                      | Strut mount with Bearing, Front RH         |    | PEUGEOT              |
| ASMPE1002K | 5038.36K  | 206   | .                                      | Strut mount with Bearing, Front LH         |   | PEUGEOT              |
| ABRRE1006  | 543251867R<br>543250005R<br>543256557R<br>54325-JA000 | MEGANE<br>SCÉNIC<br>NISSAN ALTIMA<br>NISSAN MAXIMA<br>NISSAN MURANO<br>NISSAN QUEST | 08-09-07-13<br>09-14<br>08-14<br>11-17 | Bearing, Shock absorber, Front LH/RH       |  | RENAULT<br>NISSAN    |
| ASBSB1002  | 20414AJ130  | LEGACY  | 09-14                                  | Bushing, Stabilizer, Front LH/RH           |  | SUBARU               |
| AAMTO1049  | 90385-18025   | LAND CRUISER<br>HILUX   | .                                      | Bushing, Leaf spring, Rear                 |  | TOYOTA               |
| ABTTO1028  | 13505-70011   | CAMRY 2.0/2.2<br>CARINA E<br>CORONA 2.0<br>CELICA 2.0                               | .                                      | Tensioner Pulley, Timing belt, NTN Bearing |  | TOYOTA               |
| ABTTO1025  | 88440-26100   | COROLLA 1.6/1.8<br>CORONA 1.6/2.0<br>TERCEL 1.3/1.5                                 | .                                      | Guide Pulley, V-belt, NTN Bearing          |  | TOYOTA               |



## 2019 V.03 NEW PRODUCTS

### Tenacity Auto Parts Co., Ltd.

| Part NO.  | OEM No.     | Model  | Year  | Description                            | Picture  | Make                        |
|-----------|-------------|--|---|--|--|-----------------------------|
| ABTTO1029 | 13503-63011 | COMRY 2.0/2.2<br>CORONA 2.0<br>CELICA 2.0<br>CRESSIDA 2.0<br>MR2 CARINA E/ED/II  | .   | Guide Pulley, Timing belt, NTN Bearing |   | TOYOTA                      |
| ABTTO1026 | 16603-31040 | HILUX<br>4 RUNNER<br>LAND  | .   | Guide Pulley, V-belt, NTN Bearing      |   | TOYOTA                      |
| ABTTO1027 | 88440-60110 | LAND CRUISER<br>LEXUS LX450D / 570   | .   | Guide Pulley, V-belt, NTN Bearing      |   | TOYOTA                      |
| ABTTO1030 | 88440-60070 | LAND CRUISER   | .   | Tensioner Pulley, V-belt, NTN Bearing  |   | TOYOTA                      |
| AAMVW1010 | 1J0-407-181 | GOLF<br>BORA<br>FOX<br>NEW BEETLE<br>POLO<br>SAVEIRO<br>UP!<br>VOYAGE<br>CLASICO/JETTA<br>LUPO<br>GOL TREND<br>FOX-AFRICA<br>LAVIDA<br>AUDI A1<br>AUDI A3<br>AUDI TT<br>SEAT IBIZA/ST<br>SEAT LEON<br>SEAT MII<br>SEAT TOLEDO<br>SKODA CITIGO<br>SKODA FABIA<br>SKODA OCTAVIA<br>SKODA RAPID<br>SKODA ROOMSTER | 98-14<br>99-11<br>04-16<br>00-10<br>09-16<br>10-16<br>12-16<br>09-16<br>99-15<br>04-10<br>09-16<br>04-10<br>08-13<br>12-16<br>01-07<br>99-02<br>06-16<br>00-06<br>12-16<br>99-16<br>12-16<br>07-16<br>97-11<br>13-16<br>06-15 | Bushing, Control arm, Front Low LH/RH  |  | VW<br>AUDI<br>SEAT<br>SKODA |
|           |             |  |   |  |  |                             |